



Connection offline

Technical Service Bulletin

Transaction No.: **2081725/1**

93 A6, Q6 e-tron - high-voltage electrical system fault P0C0C00_P0E8D00

Release date: Apr 22, 2026

Condition

Model(s)	Year(s)	VIN Range	Vehicle Specific Equipment
A6 Sportback e-tron, S6 Sportback e-tron, Q6 e-tron, Q6 Sportback e-tron, SQ6 e-tron, and SQ6 Sportback e-tron	2025 – 2026	All	Not applicable

Customer states:

A red warning message “High-voltage electrical system: fault. Safely stop vehicle” appears when the vehicle is started.

Workshop findings:

The following event memory entries are logged in diagnostic address 00CE (electric drive 2) and/or in diagnostic address 0051 (electric drive):

- **P0C0C00** with symptom **67083** and **67135**

AND

- **P0E8D00** with symptom **67208**

Important! All 3 entries must have been logged at same time, otherwise this TSB does not apply.

Technical Background

Not applicable.

Production Solution

Not applicable.

Service

If this complaint occurs, please replace the affected power electronics.

Warranty

Claim Type:	• If the vehicle is outside of any warranty, this Technical Service Bulletin is informational only.
Service Number:	9350
Damage Code:	0040

Labor Operations:	Rear power and control electronics	9350 1950	See SRT with associated operations
	Front power and control electronics	9350 1960	See SRT with associated operations
	GFF	0150 0060	Time stated on the diagnostic protocol
Claim Comment:	As per TSB 2081725/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Please note the information on predecessors and items that are included and excluded in the repair operations, as well as any associated tasks.

Additional Information

All part and service references provided in this TSB (**2081725**) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2026 Audi of America, LLC / Audi Canada, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.