



VOLKSWAGEN DEALER COMMUNICATION

Revision – Service Action 24TT / Engine Control Module (ECM) Software

This notice is for:	All Dealer Personnel
Date:	April 21, 2026
Revision Information:	Updated affected vehicles chart. Added note to the work instructions regarding fault code P160900.
Notes:	Please take the time to ensure everyone in your dealership with campaign-related responsibilities has thoroughly reviewed the revised circular that has been published to ELSA and Service References in Elsa2Go. Please discard any paper copies you may have printed and ensure they are replaced with the most current version.

-END OF MESSAGE-

*Ensure all dealer personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance.
Direct press inquiries to Volkswagen Public Relations.*