



VOLUNTARY SERVICE CAMPAIGN

Classification:	Reference:	Date:
RS03-009A	ITB03-068A	April 28, 2026

VOLUNTARY SERVICE CAMPAIGN AIR BAG CONTROL UNIT REPROGRAM

CAMPAIGN I.D. #: P3156

APPLIED VEHICLE: 2003 FX35 / FX45 (S50)

APPLIED VINS: Vehicles built within the following ranges:

JNRAS08U*3X 000014 to 002021
100001 to 103692

JNRAS08W*3X 000028 to 004170
200001 to 208839

JNRBS08W*3X 000051 to 003595
400001 to 404880

Voluntary Service Campaign ID # P3156 is no longer active.

- Repair orders opened after this bulletin's published date are no longer eligible for reimbursement under Campaign ID # P3156.
- Discard all previous versions of ITB03-068.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
November 26, 2003	ITB03-068	Original bulletin published
April 28, 2026	ITB03-068A	Amended to sunset