



# TECHNICAL SERVICE BULLETIN

|                 |            |                |
|-----------------|------------|----------------|
| Classification: | Reference: | Date:          |
| EC25-018A       | NTB26-006A | April 30, 2026 |

## FUEL FILLER TUBE LOWER SEAL IS LEAKING AND DTC P0456 IS STORED IN THE ECM

|                   |                                                                                                                                  |
|-------------------|----------------------------------------------------------------------------------------------------------------------------------|
| APPLIED VEHICLES: | 2025-2026 Armada (Y63)<br>2025-2026 Kicks (P16)<br>2025-2026 Murano (Z53)<br>2022-2025 Pathfinder (R53)<br>2021-2026 Rogue (T33) |
| APPLIED SYSTEMS:  | All model years with a capless fuel filler. This bulletin does not apply to vehicles with a fuel cap.                            |

**This bulletin is no longer active.**

**Please discard previous versions of NTB26-006.**

### AMENDMENT HISTORY

| PUBLISHED DATE   | REFERENCE  | DESCRIPTION                 |
|------------------|------------|-----------------------------|
| February 2, 2026 | NTB26-006  | Original bulletin published |
| April 30, 2026   | NTB26-006A | Bulletin no longer active   |