

GPOP - Issue Review System

Part Number: 68614123A\$, 68614124A\$

Part Description: Trailer steering knob

Issue Description: Trailer Reverse Steering Knob Module is triggering DTC B22AE-96 falsely due to a bug in the software. DTC B22AE-96 stands:
Trailer Reverse Steering Knob Module Internal Performance Component Internal Failure and it means "Backlight LED failure, short circuit between backlight LEDs etc". Please, follow SOL S2608000025 for part TRSKM replacement, depending on conditions explained.