

V O L V O

Volvo Car USA LLC

Technical Journal

Technical Journal Title Propulsion Message with DTC IEM P060700 and/or P061A00		Ref. No. TJ 37495.3.0	
Issuer (Dept.) Technical Service		Issue Date 6/10/26	Status Date 6/22/26
Car Market United States and Canada	Partner 3 US 7510 Volvo Car USA	Function Group 3233	
Function Description Electric converter, high voltage		Page Page 1 of 2	

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

*VST Operation No and "Service" section updates.

If a customer experiences a "Propulsion System Performance" message in the DIM with diagnostic trouble code IEM P060700, often in combination with IEM please follow the instructions under "Service".

CSC Customer Symptom Codes

Code	Description
IV	Text window and warning symbol/Text message
DL	Warning lights and chimes/Malfunction Indicator Light ("Check engine" light) indication/no indication

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
IEM	P061A00	Permanent
IEM	P060700	Permanent

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224	H6	BH6PHEV					2022-2023		-	202147-202316
225	H6	BH6PHEV					2022-2023		-	202147-202316
238	H6	BH6PHEV					2022-2023		-	202147-202316
246	H6	BH6PHEV					2022-2023		-	202147-202316
256	H6	BH6PHEV					2022-2023		-	202147-202316

Technical Journal 37495.3.0

SERVICE:

***Improved software has been released in version 5.1.9.**

*Perform a software upgrade according to TJ 31543.

Abbreviations:

IEM = Inverter Electric Rear Axle Drive Module

DIM = Driver Information Module

Warranty claim info:

To get a warranty claim accepted for a job described in this TJ, use the corresponding VST OP number stated in this TJ.

Please note that fault tracing is not eligible for separate reimbursement under this TJ. Any fault tracing VST operation numbers will be rejected. Note, that the TJ number must be stated in the repair order text.

VST Operation Number

VST Operation Number	Description
98821-3	Software download acc. to TJ

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use the concern area "Vehicle Report" and the sub-concern area "Support Needed", use function group 3233.