

REFERENCE:	TSB: 08-312-26 GROUP: 08 - Electrical	Date:	August 7, 2026	REVISION:	See Revision Statement
VEHICLES AFFECTED:	2024 - 2025 (KM) Wagoneer S This bulletin applies to vehicles equipped with 400V G2500 FR/RR Elec Drive Motors (Sales Code ELD).			MARKET APPLICABILITY: ☒ NA☐ MEA ☐ SA☐ IAP ☐ EE☐ CH NOTE: This bulletin applies to North America markets.	
CUSTOMER SYMPTOM:	Customers may experience a Malfunction Indicator Lamp (MIL) illumination and the vehicle may exhibit/set one or more of the following Diagnostic Trouble Codes (DTCs): - P1E18-00 - Internal Control Module Electronic Park Performance. - P1625-00 - Park Pawl System Failure. - P1626-00 - Park Pawl Motor Stuck. NOTE: If DTCs P1E25-00, P1625-00 or P1626-00 are active, the vehicle will stay in READY mode since the Electric Vehicle Control Unit (EVCU) is not able to confirm if the park pawl is engaged, and the vehicle will be secured. - P0A78-00 - Drive Motor A Inverter Performance. - P0A79-00 - Drive Motor B Inverter Performance. Customers may also comment on one or more of the following: - Vehicle is not shutting off and draining the 12V battery. - Unable to start the vehicle.				
CAUSE:	Software				

This bulletin supersedes the following Technical Service Bulletins (TSBs), which should be removed from your files. This is a complete revision and no asterisks have been used to highlight revisions.

08-010-25 REV. E, date of issue December 18, 2025.

08-011-25 REV. D, date of issue December 18, 2025.

08-013-25 REV. E, date of issue December 18, 2025.

08-014-25 REV. E, date of issue December 18, 2025.

08-074-25 REV. D, date of issue December 18, 2025.

08-076-25 REV. D, date of issue December 18, 2025.

08-077-25 REV. D, date of issue December 18, 2025.

08-078-25 REV. C, date of issue December 18, 2025.

08-127-25 REV. C, date of issue December 18, 2025.

08-129-25 REV. C, date of issue December 18, 2025.

08-132-25 REV. B, date of issue December 18, 2025.

08-128-25 REV. B, date of issue December 18, 2025.

08-134-25 REV. B, date of issue December 18, 2025.

08-206-25 REV. C, date of issue August 30, 2025.

08-207-25 REV. D, date of issue August 30, 2025.

08-409-25, date of issue December 18, 2025.

08-410-25, date of issue December 18, 2025.

DISCUSSION:

These listed bulletins are no longer applicable due to the publication of CSNs 74D, 79D and 80D. Refer to the CSN for detailed repair procedure instruction and labor times.

POLICY:

Information Only.

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.