



Service Bulletin

Bulletin No.: PIT6517E

Date: August, 2026

PRELIMINARY INFORMATION

Subject: B174 Front View Camera Module (FCM) DTC U3000 Part Restriction Has Ended

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Colorado	2024–2026		All	All	All	All
Chevrolet	Corvette	2024–2025		All	All	All	All
GMC	Canyon	2024–2026		All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment on having the Service Engine Soon (SES) and/or Malfunction Indicator Lamp (MIL) illuminated. When checking for DTCs the B174W Front View Camera (FCM) will have a U3000 as history.
Cause	Software anomaly in the B174W Front View Camera Module.

Correction

General Motors Product Quality Center (PQC) part restriction on B174 Front View Camera Module (FCM) has ended.

We would like to thank all dealers who participated in this restriction for their cooperation.

This B174 Front View Camera Module (FCM) can now be ordered through the regular GM CCA parts process or PQC process for required dealers (Canada).

Version	5
Modified	05/28/2026 - Created on 06/05/2026 - Updated title/subject line. 07/14/2026 - Updated Q5 07/30/2026 - Updated models and years 08/18/2026 - Updated models and years 08/24/2026 - Updated to end the restriction

