

Check Engine MIL with DTC P026B	2019/2020 Range Rover and RR Sport MHEV
<u>Customer Voice:</u> • The Check Engine MIL is on. <u>Technical Description:</u> • P026B and a cylinder specific Injector Timing DTC stored in the PCM. <u>Status:</u> • Fix in development • Inspect injector connectors pay close attention to terminal tension and seating in the connector housing - drag test and compare to cylinders that are not setting an individual cylinder DTC. • Check the ground circuit for the individual injector setting the DTC paying close attention also to terminal tension at the PCM connector C1E122A. • If no fault is identified a revised PCM calibration will be released to resolve this by the end of January.	