

**ATTENTION:**

GENERAL MANAGER ☐  
PARTS MANAGER ☐  
CLAIMS PERSONNEL ☐  
SERVICE MANAGER ☐

IMPORTANT - All  
Service Personnel  
Should Read and  
Initial in the boxes  
provided, right.

|  |  |  |
|--|--|--|
|  |  |  |
|  |  |  |

©2019 Subaru of America, Inc. All rights reserved.

**SUBARU****QUALITY DRIVEN® SERVICE****SERVICE BULLETIN**

**APPLICABILITY:** 2015MY Impreza  
2015MY Crosstrek  
2015MY Legacy and Outback

**SUBJECT:** DTC B280B- EyeSight Camera Reprogramming  
File Availability

**NUMBER:** 07-158-19R

**DATE:** 08/26/19

**REVISED:** 02/21/20

**IMPORTANT:** This Service Bulletin has been as been replaced by TSB 07-170-20 dated 02/21/2020 entitled "Reprogramming File Availability for EyeSight DTC B280B: VDC Abnormal". Please refer to this new bulletin for the latest information regarding this condition.

**CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD  
RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.**

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

**Subaru of America, Inc. is  
ISO 14001 Compliant**

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.