



Technical Journal

TITLE:

DTC CEM-U030141 with no customer symptomREF NO:
TJ 34676.2.0ISSUING DEPARTMENT:
Technical ServiceCAR MARKET:
United States and CanadaPARTNER:
3 US 7510 Volvo Car USAISSUE DATE:
2020-02-19STATUS DATE:
2020-02-24FUNC GROUP:
3720FUNC DESC:
**Electrical distribution box,
fuse box**

Page 1 of 2

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
134							2015-2019		-	201420-999952
137							2015-2019		-	201420-999952
155							2015-2019		-	201420-999952
156							2015-2019		-	201420-999952
157							2015-2019		-	201420-999952

CSC Customer Symptom Codes

Code	Description
3L	Technician information/Repair information/Not for warranty use
2V	Technician information/Software/Vehicle communication/Not for warranty use

VST Operation Number

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
CEM	U030141	Intermittent

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.



Text

DESCRIPTION:

CEM = Central Electronics Module

PDS = Pre-Delivery Service

DTC CEM-U030141 may be stored after service software is downloaded to the vehicle (Total Upgrade, Service 2.0, PDS)

No customer-visible symptoms.

SERVICE:

This DTC can be ignored. No fault tracing or repair is necessary.

Warranty claim info:

No warranty claim accepted for a job described in this TJ.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3720.