

SSM 48633 - 2018-2019 Transit - 3.2L Diesel Engine - Illuminated Malfunction Indicator Lamp (MIL) With Diagnostic Trouble Code (DTC) P2452 And/Or P2453

Some 2018-2019 Transit vehicles equipped with a 3.2L diesel engine may experience an illuminated MIL with DTC P2452 and/or P2453 stored in the powertrain control module (PCM). Engineering is working to implement a solution for this condition. In the interim, clear the DTCs with the appropriate Ford scan tool. Advise the customer that a repair is expected to be available mid-May 2020 and that the condition has no effect on vehicle operation or long term durability. Dealers are asked to follow-up with their customers to schedule a service appointment once a TSB is published.