

GPOP - Issue Review System

Part Number: 68199324A\$

Part Description: SENSOR, Map

Issue Description: For MAP sensor diagnostic trouble code DTC P0069, please contact *FCA Redacted Content* prior to repair.

If no response in 15 minutes, proceed with repair.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
~