

GPOP - Issue Review System

Part Number: 6QE18TX7A\$

Part Description: SWITCH, Ignition, Push Button (Keyless Ignition Node)

Issue Description: Prior to replacing parts for a B1A7D-2A Diagnostic trouble code on heavy duty trucks. Please call FCA Redacted Content , please email a scan and config report to FCA Redacted Content.

If no response in 15 minutes, proceed with repair.

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
