

GPOP - Issue Review System

Part Number: 5NL22TZZA\$, 1TK84TZZA\$

Part Description: SENSOR, Park Assist

Issue Description: For diagnostic issues relating to any of the following Park Assist error conditions:
·SERVICE PARK TRONICS ON CLUSTER
·VEHICLE WITH FAULT B1297-12-PTS SENSOR.
·CUSTOMER STATES PARK ASSIST NOT WORKING WITH SENSOR INOP

The Product Development team requests that photos be taken of any suspected failed sensors before any repair to the sensor is started on the vehicle. Also, please email a copy of the VSR and sensor photos to the following FCA engineers:

FCA Redacted Content

We will review the scan report and photos, and let you know the next steps as soon as we can. If no response in 15 minutes, proceed with repair.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

