

SSM 48896

2020 Corsair - Various DTCs Stored In The Remote Function Actuator (RFA) Module

Some 2020 Corsair vehicles may exhibit diagnostic trouble codes (DTCs) P1269, B1A56, B1D55, B1589, and/or B1590 through B1598 stored in the RFA module with no detectable customer symptoms. If these DTCs are detected during pre-delivery inspection (PDI) or while diagnosing unrelated conditions, they should be ignored.

Vehicles:

2020 Corsair (CX483) (TF)