

On-car analysis list from July 10th, 2020
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Jetta	19-20	1.4T (DGXA / DJXA)	All	MIL-on P0496	Customer states MIL-on (Must have P0496 in the ECM)
	Jetta	19-20	1.4T (DGXA / DJXA)	All	MIL-on U0284	Customer states MIL-on (Must have U0284 in the ECM) (untouched vehicles)
	Atlas, Atlas Cross Sport	19-21	3.6L (CDVC)	All	Engine Oil Leak	Customer states engine oil leak (leaking from cylinder head valve cover ONLY) (untouched vehicles)
	Jetta, Golf, SportWagen	19-20	1.4T (DGXA / DJXA)	All	Engine Oil Leak	Customer states engine oil leak (UPPER or LOWER ENGINE OIL PAN ONLY) (untouched vehicles)
	Jetta	18	1.4T (CZTA)	All	MIL-on P0111	Customer states MIL-on (Must have P0111 in the ECM) (untouched vehicles)
	Tiguan	20	2.0T (DGUA)	All	MIL-on P0442	Customer states MIL-on (Must have P0442 in the ECM)
	Jetta GLI, Golf GTI, Tiguan	19	2.0T (DKFA, DGUA)	All	HPFP Bolt	Customer states MIL-on, HPFP mounting bolts loose/broken (HPFP bolts must be loose/broken)
Electrical	Passat	19-20	All	All	No Terminal 15	Customer states "No Crank/No Start" (untouched vehicles)
Body	Jetta	19	All	All	Headlights cracked	Customer states both headlights are cracked (untouched vehicles) (CANNOT have outside influence)
	Atlas	19-20	All	All	Wind Noise	Wind Noise from the Front Driver or Passenger Door (untouched vehicles) (CANNOT have outside influence)
Other	Jetta, Jetta Wagon, Jetta SportWagen, Golf, Golf Wagon, Beetle, Beetle Convertible	09-14	2.0 TDI (CJAA/CBEA)	All	TB Data P0401	Customer states MIL-on (Must have P0401 in the ECM) (Must be performing TB 01-18-13 / 2034898) (concern group TDI Emissions) <u>(Fill out attachment in VTA: Gen I-TDI Survey)</u>