

SSM 49153 - 2019-2020 Mustang - 5.0L Engine - Various Manual Transmission Related DTCs - Updated WSM Diagnostics

Some 2019-2020 Mustang vehicles equipped with a 5.0L engine and a manual transmission may exhibit a malfunction indicator lamp (MIL) with diagnostic trouble codes (DTC's) P086A, P086B, P086C, P086D P086E, P08AE, P08AF, P08B0, P08B2, P095A,P095B, P095C and/or P095D present. Workshop Manual (WSM) diagnostics have recently been updated to assist in better diagnosis of these DTCs. Refer to WSM, Section 308-03A.

APPLICABLE VEHICLES

2019 - 2020 CAR: ZG S550N MUSTANG

2019 - 2020 CAR: ZG S550N MUSTANG