



Bulletin No.: PIP5754  
Published date: 09/28/2020

# Preliminary Information

## PIP5754 Malfunction Indicator Lamp (MIL) Illuminated with DTC P262B

### Models

| Brand:   | Model: | Model Years: | VIN: |     | Engine:  | Transmissions: |
|----------|--------|--------------|------|-----|----------|----------------|
|          |        |              | from | to  |          |                |
| Cadillac | CT6    | 2019 - 2020  | All  | All | 4.2L LTA | All            |

|                            |                                                                                                                                                                                                                                     |
|----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Involved Region or Country | North America                                                                                                                                                                                                                       |
| Condition                  | Some customers may comment that the SES lamp is illuminated or was illuminated and turned off. During inspection Technician may find DTC P262B (Control Module Power Off Timer Performance) active or stored in history.            |
| Cause                      | This condition may be caused by the engine cooling down quicker than what the ECM expects after the vehicle is shut off and then restarted. This can occur in a windy area or if pulled into an air-conditioned garage for example. |

### Correction:

If a vehicle comes in with this DTC set, do not replace the ECM for this condition. Engineering is aware of the condition and is working on a revised diagnostic calibration to address. Clear the code and release the vehicle back to the customer.

### Warranty Information

| Labor Operation                                          | Description                             | Labor Time |
|----------------------------------------------------------|-----------------------------------------|------------|
| *4087608                                                 | Check ECM for DTC P262B and Clear Codes | 0.3 Hr.    |
| *This is a unique Labor Operation for Bulletin use only. |                                         |            |

### Version History

|          |                         |
|----------|-------------------------|
| Version  | 1                       |
| Modified | 09/28/2020 - Created on |

