

SSM 49386: 2020-2021 Police Interceptor Utility - DTCs C0052, C0053, C0054, And/Or C0055 Stored In The Trailer Module (TRM)

Some 2020-2021 Police Interceptor Utility vehicles may have diagnostic trouble codes (DTCs) C0052, C0053, C0054 and/or C0055 stored in the TRM if the police steering wheel output circuits are not connected to any accessories. If these DTCs are detected during diagnosis of unrelated concerns, they should be ignored.

Vehicles:

2020-2021 Explorer (U625N) (TW)

Symptom Code:

C0052

C0053

C0054

C0055