

SSM 49390: 2019-2020 Transit Connect - DTC U0151 Stored In SYNC Module - Built On Or Before 29-Jun-2020

Some 2019-2020 Transit Connect vehicles built on or before 29-Jun-2020 may have a diagnostic trouble code (DTC) U0151 stored in the SYNC Module (Accessory Protocol Interface Module). If no other codes are present and a U0151 code remains after clearing, do not attempt any further repairs. This code does not impact the performance or reliability of the vehicle and will not induce a customer indicator.

Vehicles:

2019-2020 Transit Connect | Tourneo Connect (HC)

Symptom Code:

112000 BODY LATCHES/LOCKS & SECURITY

U0151