



Technical Service Bulletin

96 "Audi Active Lane Assist/Traffic Jam Assist: malfunction!", DTC U112300 is stored in one of two control modules

96 21 61 2061932/1 January 19, 2021.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q5, SQ5	2021	All	Capacitive steering wheel
Audi e-tron quattro	2019 - 2023	All	Capacitive steering wheel
Audi e-tron Sportback	2020 - 2023	All	Capacitive steering wheel
A5, A5 Cabriolet, A5 Sportback, S5, S5 Cabriolet, S5 Sportback, RS 5 Cabriolet, RS 5 Sportback, A7, S&, RS 7, A8, S8, Q7, SQ7, Q8, SQ8, and RS Q8	2021 - 2023	All	Capacitive steering wheel

Condition

Customer states:

Either of the following malfunction indications are displayed in the instrument cluster:

- "Audi Active Lane Assist: malfunction!"

Or

- "Traffic Jam Assist: malfunction!"




Figure 1. Example of a message.



Technical Service Bulletin

Workshop findings:

One or more of the following DTC(s) may be stored relating to the front camera, R242 (address word 00A5) and distance regulation control module, J428 (address word 0013):

Front camera, R242 (address word 00A5):

- **DTC U112300** (Databus error value received) with symptom code 1123220.

Distance regulation control module, J428 (address word 0013):

- **DTC U112300** (Databus error value received) with symptom code 2153.

Technical Background

These vehicles are equipped with a “capacitive steering wheel” that detects the driver’s hands on the wheel with capacitive touch sensors. This is used to make sure that the driver is paying attention when using driver assist features.

Production Solution

Not applicable.

Service

The two DTCs U112300 mentioned in the condition point to a malfunction of the capacitive steering wheel.

1. Inspect the steering wheel for exterior, mechanical damage, like deep scratches.
2. If mechanical damage is found, this is due to external influence and may not be covered under warranty.
3. Remove the airbag from the steering wheel.
4. Make sure that all wiring visible on the steering wheel is in good condition and that all connectors are properly secured.
5. After completing steps 1 through 3 and not finding any obvious damage, then replace the steering wheel.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.
--------------------	---



Technical Service Bulletin

Service Number:	4810		
Damage Code:	0040		
Labor Operations:	Driver airbag unit remove + reinstall	6958 1900	See SRT with associated operations
	Inspecting steering wheel for damage	4810 1999	5 TU
	Steering wheel remove + reinstall (if required)	4810 1900	See SRT with associated operations
Diagnostic Time:	GFF	0150 0000	Time stated on the diagnostic protocol (Max 15 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2061932/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
See ETKA	Steering Wheel (if required)	01

Additional Information

All parts and service references provided in this TSB (2061932) are subject to change and/or removal.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property



Technical Service Bulletin

rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.