



SERVICE BULLETIN

Classification:

EL15-043

Reference:

NTB15-116

Date:

December 22, 2015

2016 TITAN XD DIESEL; BATTERY DISCONNECT WAIT TIME / DTCS P2509 & P181B


APPLIED VEHICLES: 2016 Titan XD (A61)

APPLIED ENGINE: Cummins 5.0L Turbo Diesel

SERVICE INFORMATION

When disconnecting either of the 12 volt batteries on the Titan XD Diesel, follow these steps:

1. Turn the ignition OFF.
2. **Wait at least 2 minutes.**
3. Disconnect battery (negative cable first).



NOTE:

- If the above steps are not followed, DTCs P2509 and P181B may be stored.
- If these codes are stored because the battery disconnection was done without waiting 2 minutes, they can be cleared, but it is not a warrantable repair.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.