

SSM 49778 - 2021 E-Series/F-Super Duty/F-650/F-750 - 6.2L/7.3L Engine - Illuminated MIL - DTC P0457

Some 2021 F-Super Duty/F-650/F-750 and 2021-2022 E-Series vehicles equipped with a 6.2L or 7.3L gasoline engine may exhibit an illuminated malfunction indicator lamp (MIL) with diagnostic trouble code (DTC) P0457 stored in the powertrain control module (PCM). This may be due to a loose fuel filler cap. The fuel filler cap design changed for 2021 to require three full turns to properly tighten. Advise the customer of the design change. For further diagnostics, refer to the Powertrain Control/Emissions Diagnosis (PC/ED) manual, pinpoint test HX.

Vehicles:

2021-2022	E-Series (VN127) (E4)
2021	F-650/750 (H567) (BC)
2021	F-Super Duty (P558) NA (FE)