

9003779

11/29/2017

MY13, 14, 17, 18

DJ, D2

GPOP - Issue Review System

Part Number: 68087105A\$, 68224930A\$, 68225236A\$

Part Description: Diesel Particulate Filter (DPF) Assembly

Issue Description: For Cummins equipped vehicles ONLY: If a customer comes in with a check engine light for P2002 which has led to replacing the DPF, please contact Dean Armstrong at cell (248) 202-8148. Cummins engineering is currently investigating the root cause to this condition.

If you do not receive an answer or call back within 15 minutes, proceed with the repair.

~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
