

9003826

11/29/2017

MY15 - 17

KL

GPOP - Issue Review System

Part Number: 68197298A\$

Part Description: 2.4L KL Cooling fan

Issue Description: If replacing the cooling fan for a P0480 -Cooling Fan 1 Control Circuit fault code or inoperative fan, please call Sam Zarnegar at (248) 944-5703 prior to removing any parts. If there is no response within 15 minutes, please leave a voicemail, or send an email to Sam.Zarnegar@fcagroup.com and continue with repair. Please include the VIN of the vehicle in all communication. Please return removed parts to FCA QEC for further analysis.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
~
