

9003690 03/08/2017 RU

GPOP - Issue Review System

Part Number: 68217818A\$, 68217819A\$

Part Description: RF Hub Module (RFHM)

Issue Description: Engineering is investigating the stored DTC: U103C-00: Keyless Ignition Node communication.~
Prior to replacing key fobs / KIN / RFHM please contact Amr Mostafa on cell: (248) 856-8455. ~

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
