

June 1, 2016 MY 16 JK

GPOP - Issue Review System

Part Number: 68065575A\$

Part Description: Fuel Pump

Issue JK ONLY: If a customer has a P0461 fault code (Fuel level sensor 1 performance)
Description: please take a picture of the fuel module orientation / alignment to the fuel tank flange as it is received. Send the picture to Bob.Bruni@fcagroup.com. Upon module removal inspect and determine if the float travel has been hampered by contact with the tank walls or internal line. Engineering is trying to determine if misoriented module will illuminate a P0461 FC. Please include the VIN with the picture.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
