

GPOP - Issue Review System

Part Number: 04672756A\$, 68516026A\$, 68425497A\$, 68452956A\$

Part Description: CAMERA, Rear View

Issue Description: Prior to replacing the RVCN (rear view camera module) due to the presence of the STORED DTC B2299-00 "Rear Camera Module Internal" on the 21MY WL75 and or 22MY WL74, WS and MP vehicles, verify there are no observable issues with the Rear View Camera feature. If there are no observable issues with the Rear View Camera feature, and no customer complaints related to the Rear View Camera, clear the STORED fault and do not replace the camera. This issue is due to a temperature detection error and will be corrected in a subsequent SW release

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.