

9/28/2016

MY14, 15, 16

DS, WK

GPOP - Issue Review System

Part Number: 52029737A\$, 68161432A\$, 68184663A\$, 68234984A\$

Part Description: TANK, Diesel Exhaust Fluid, Part Includes Temp Sensor and Level Sensor

Issue Description: For DS and WK vehicles ONLY; If the urea tank is being replaced due to P249C, P203E, or P24F3 on a 2014-2016 model year 3.0L Turbo Diesel (EXF) on DS or WK, please call Indra Djutrisno at cell (248) 892-3473. If no response is received within 15 minutes, please continue with repair.~

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
