

9003766 08/02/2017 MY17 MP

GPOP - Issue Review System

Part Number: 68292767A\$, 68292771A\$

Part Description: PTU

Issue If vehicle displays code C2270-77 please call Ashley Gerebics @ (248) 472-6524. If

Description: no response within 15 minutes, please proceed with replacement of entire PTU unit.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP
Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the
Tech Tip you are referencing for our tracking system.
~
