

8/24/2016 MY15, 16 BU MY16 FB

GPOP - Issue Review System

Part Number: 68321236A\$, 68321233A\$

Part Description: RF Hub Module

Issue Description: DTC, U1765-87 "RFHM (Radio Frequency Hub Module) - Missing Message" may appear in a stored state on a ignition power cycle. No troubleshooting or parts replacement is necessary if this code is stored as the system is functioning to design.~

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
