

9003789

10/04/2017

MY15 - 18

KL

GPOP - Issue Review System

Part Number: 5YD27LS5A\$, 5YD27XSAA\$, 5YD28LS5A\$, 5YD28XSAA\$, 5YD271UWA\$

Part Description: KL Gear Shift Module

Issue Description: For 2015-2018 KL ONLY; If vehicle DTC Code P1C86-1D (PRNDL Display Current out of Range) is verified as either stored or active please contact Pablo Flores in FCA Chassis Engineering at cell (248) 979-7062. If no response in 15 minutes, proceed with repair. For additional repair see NOTES below:

NOTE 1: If DTC P1C86-1D is still active after inspecting harness connections from Service Procedure (STEP 2). DO NOT replace SHIFTER ASSEMBLY. Instead, replace PRNDM bezel only.

NOTE 2: After replacing PRNDL Assembly, clear DTCs and check to confirm DTC does not return.

Please return parts back to FCA Engineering if PRNDM is deemed non-functional after performing this TechTip. For 2015-2018 KL ONLY; If vehicle DTC Code P1C86-1D (PRNDL Display Current out of Range) is verified as either stored or active please contact Pablo Flores in FCA Chassis Engineering at cell (248) 979-7062. If no response in 15 minutes, proceed with repair. For additional repair see NOTES below:

NOTE 1: If DTC P1C86-1D is still active after inspecting harness connections from Service Procedure (STEP 2). DO NOT replace SHIFTER ASSEMBLY. Instead, replace PRNDM bezel only.

NOTE 2: After replacing PRNDL Assembly, clear DTCs and check to confirm DTC does not return.

Please return parts back.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
