

9003793

10/04/2017

MY17

RU

GPOP - Issue Review System

Part Number: 56054252A\$, 56054253A\$

Part Description: Steering Column Control Module (SCCM)

Issue Description: Check for stored B2225 code when you scan the vehicle in service. If you see this code stored; clear the DTC. If the stored Fault reappears, please call Ivan Ramos cell (248) 817-0468 prior to replacing the SCCM. If you don't receive response please leave a voice mail, if no further response within 15 minutes continue with normal repair procedure.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.