

9003803 10/18/2017 MY17 JC

GPOP - Issue Review System

Part Number: 05149264A\$

Part Description: Ambient Temperature Sensor

Issue Description: If replacing an ambient temperature sensor on 2017 JC (Journey) for P0070, P0071, P0072, or P0073 fault codes, please call Omar Jobe at cell (248) 910-2166. If you do not receive a response within 15 minutes, please proceed with repair.

Digital images of any physical issue discovered would be very helpful. Please send digital images to email address: omar.jobe@fcagroup.com.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
