



STAR ONLINE PUBLICATION



Case Number: S2208000162

Release Date: September 2022

Symptom/Vehicle Issue: Check Engine Lamp (CEL) on Diagnostic Trouble Codes (DTC's) P0073 Ambient Air Temperature Sensor Circuit High, U113D-00 Lost Communication with Master Power Window Switch

Technician Observation: After a recent service repair the vehicle sets DTC's P0073 Ambient Air Temperature Sensor Circuit High, U113D-00 Lost Communication with Master Power Window Switch.

Discussion: Vehicles that are built for export with sales code (ABF) New Zealand Equipment Group are built as a left-hand drive vehicle. The vehicles are then shipped to Walkinshaw Automotive Group an upfitter in Australia to be converted to a right-hand drive vehicle.

If these vehicles have a vehicle reconfiguration performed prior to the official conversion the vehicle configuration data will update to a right-hand drive vehicle setting the above DTC's. Do not replace any parts for this concern.

Vehicle Line	DS	
Country Code	Rest of World	
Left/ Right Hand Drive	Right Hand Drive	✓
Remote Start Present	Not Set	
Drive Configuration	Selectable 4WD	

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechConnect, eCONTACT or Service Library entry if no solution is found.