

GPOP - Issue Review System

Part Number: 68602151A\$

Part Description: SENSOR Exhaust Temperature

Issue Description: If this sensor is being replaced due to an early-life P242B pending fault code, clear the fault code and perform the Powertrain Verification Test. Only replace the sensor if P242B returns as an active fault code.