



Preliminary Information

PIP4582A DTC P0101 Mass Air Flow (MAF) Sensor Performance

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Saturn	Vue	2009	All	All	3.6 LY7	All

Supersession Statement

This PI was superseded to update review date. Please discard PIP4582.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

The vehicle may have a concern of SES light illuminated w/diagnostic code P0101 (Mass Air Flow (MAF) Sensor Performance) stored.

Check for Engine Air Box (Air Cleaner) internal diffuser being detached and/ or fallen down out of position onto air filter element.

Recommendations / Instructions

Replace the air box if diffuser is detached.

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.

