

On-car analysis list from February 13th, 2017
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Passat	14-17	1.8T (CPKA/CPRA)	All	MIL-on P2407	MIL-on fault P2407 in the ECM (untouched vehicles)
	Passat, Beetle, Jetta	14-17	1.8T (CPKA/CPRA)	All	Oil pressure warning with P164D	Oil pressure warning with P164D in the ECM (Must have fault in the ECM) (Must have oil in the connector of the oil pressure switch)
Chassis	Jetta	16-17	All	All	Rear Brake Caliper	Rear brake noise, dragging, excessive dust (untouched vehicles)
Body	Passat	16	All	All	Instrument Panel Noise	Instrument panel noise (untouched vehicles after VIN HC011431)
	Passat	16 - 17	All	All	Trunk latch (release) inoperative	Trunk latch will not release with key fob, button in the door, on the trunk or with easy open feature (foot release).
	Golf/GTI	16 - 17	All	All	Sunroof Motor Loss Basic Settings	Sunroof controls malfunctioning
	Golf/GTI	16 - 17	All	All	Sunroof Squeak/Rattle	Sunroof squeaks/rattles with the sunroof in closed position
	Passat	16-17	All	All	Door Noise	Door(s) noise (untouched vehicles after VIN GC052150)