

On-car analysis list from March 15th, 2017
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Passat	14-17	1.8T (CPKA/CPRA)	All	MIL-on P2407	MIL-on fault P2407 in the ECM (untouched vehicles)
	Touareg	16-17	All	All	Coolant leak from coolant pump	Coolant leak from the coolant pump (untouched vehicles)
	Passat, Beetle, Jetta	14-17	1.8T (CPKA/CPRA)	All	Oil pressure warning with P164D	Oil pressure warning with P164D in the ECM (Must have fault in the ECM) (Must have oil in the connector of the oil pressure switch)
Chassis	Jetta	16-17	All	All	Rear Brake Caliper	Rear brake noise, dragging, excessive dust (untouched vehicles)
	Jetta	17	All	All	Brake Hissing	Hissing noise when pressing the brake pedal (untouched vehicles)
	GTI	16-17	All	6 Spd Standard	Clutch pedal squeak	Customer states the clutch pedal squeaks when operated (after VIN 3VWYT7AU0GM068470)
Body	Passat	16	All	All	Instrument Panel Noise	Instrument panel noise (untouched vehicles after VIN HC011431)
	Passat	16 - 17	All	All	Trunk latch (release) inoperative	Trunk latch will not release with key fob, button in the door, on the trunk or with easy open feature (foot release).
	Golf/GTI	17	All	All	Sunroof Squeak/Rattle	Sunroof squeaks/rattles with the sunroof in closed position
	Jetta, Beetle	16 - 17	All	All	A/C Inoperative	A/C inoperative, compressor found to be locked up (compressor has to be seized) (untouched vehicles)
	Passat	16-17	All	All	Door Noise	Door(s) noise (untouched vehicles after VIN GC052150)