

Classification:

Reference:

COPYRIGHT© NISSAN NORTH AMERICA, INC.
Date:

EL18-045

ITB19-001

January 11, 2019

CHASSIS CONTROL MODULE DTC INFORMATION

APPLIED VEHICLES: 2014-2019 Q50 (V37)
 2014-2018 Q50 Hybrid (HV37)
 2017-2019 Q60 (CV37)

SERVICE INFORMATION

If one or more of the following Chassis Control DTCs are stored:

- C1BA0-00 – (CHASSIS CONTROL BRAKE SYSTEM)
- C1B90-00 – (DIRECT ADAPTIVE STEERING SYSTEM)
- C1B92-00 – (BRAKE CONTROL SYSTEM)
- C1B93-00 – (ENGINE/HEV SYSTEM)
- C1B94-00 – (TRANSMISSION SYSTEM)

And

One or more additional DTCs, other than those above, are also stored in a control unit other than the Chassis Control Module.

- Perform the diagnostic/repair procedures for the additional DTCs of the other control unit **FIRST**.
 ➤ Refer to the Electronic Service Manual (ESM) for DTC specific diagnostic information.

Do not replace the CHASSIS CONTROL MODULE (CONTROLLER ASSY-IDM) if additional DTCs are present.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
January 11, 2019	ITB19-001	Original bulletin published

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.