



# SERVICE CAMPAIGN BULLETIN

Classification:

BT11-041a

Reference:

NTB12-002a

Date:

January 24, 2019

## VOLUNTARY SERVICE CAMPAIGN 2011 – 2012 MURANO CROSS CABRIOLET; SOFT TOP OUTER FLAP ADJUSTMENT BOLT

**CAMPAIGN I.D. #:** P1258 (Inactive)

**APPLIED VEHICLES:** 2011 – 2012 Murano Cross Cabriolet (EZ51)

### Voluntary Service Campaign ID # P1258 is No Longer Active.

- Repair orders opened after January 24, 2019 are no longer eligible for reimbursement under Campaign ID # P1258.
- Please discard previous versions of NTB12-002.

### AMENDMENT HISTORY

| PUBLISHED DATE   | REFERENCE  | DESCRIPTION                                  |
|------------------|------------|----------------------------------------------|
| January 4, 2012  | NTB12-002  | Original bulletin published.                 |
| January 24, 2019 | NTB12-002a | Voluntary Service Campaign no longer active. |