



Preliminary Information

PIP5565B Check Engine Light On With DTC P140B

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado	2017 - 2018	All	All	6.6 L5P	All
GMC	Sierra	2017 - 2018	All	All	6.6 L5P	All

Involved Region or Country	North America
Condition	Some customers may comment on a Service Engine Soon Light / Check Engine Light on.
Cause	Technician may find DTC P140B set with no additional DTCs set.

Correction:

Check for any open recalls, service updates or campaigns on the vehicle.

If recalls, service updates or campaigns are open perform those and use the corresponding labor operations to close those out.

If there are no open recalls, service updates or campaigns and the vehicle is a 2018 model year check for and perform any available ECM calibration updates.

If there are no open recalls, service updates, campaigns or ECM calibration updates, refer to service information for diagnosis of the concern.

If the vehicle is a 2017 model year and there are no available ECM calibration updates, open recalls, service updates or campaigns please clear the DTC and return the vehicle to the customer. GM engineering is aware of the concern and is investigating.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
4029959	Emissions - Customer Concern Not Duplicated (CCND)	Use Published Labor Time

Version History

Version	3
	04/11/2018 - Created
	9/25/2018 - Updated to add unique labor operation.
Modified	12/04/2018 - Updated to refer to service update N182179090 for 2018 model year vehicles and to use labor operation 4029959 Emissions - Customer Concern Not Duplicated (CCND) for 2017 model year vehicles



GENERAL MOTORS