



Service Bulletin

File in Section: -

Bulletin No.: PIE0481A

Date: November, 2018

ENGINEERING INFORMATION

Subject: Engineering Information – Check Engine Light and/or Service Steering Message on Driver Information Center (DIC), Higher Steering Efforts, DTCs C0545 and/or C0460 Set

This PI has been revised to end the need for information from the field. Please discard PIE0481.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu	2009	2012			Equipped with 2.4L Engine (RPOs LE5, LE9)	
Pontiac	G6		2010				
Saturn	Aura						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released August 16, 2018 Revised November 01, 2018 – Ended the need for further information from the field.