



Technical Service Bulletin

96 Audi adaptive light system malfunction

96 19 33 2054202/1 March 8, 2019.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7, A8, and Q8	2019	All	Not Applicable

Condition

Customer states:

- The message “Audi adaptive light: system fault!” is displayed in the instrument cluster (Figure 1).



Figure 1. Instrument cluster message.

Workshop findings:

The following DTCs may be stored in the control module for driver assistance systems (address word 00A5):

- DTC C12B3FA** (front camera for driver assist systems - communication fault) with symptom code 221189.
- DTC C12B3FB** (front camera for driver assist systems – malfunction) with symptom code 221187.

Technical Background

This software needs to be updated. This is a rare scenario, which causes a warning.

Production Solution

Software in preparation.

Service

- Delete the DTC(s).



Technical Service Bulletin

2. After deleting the DTC(s) the concern is fixed and is unlikely to reoccur.



Note:

A replacement of the front camera for the assistance systems R242 does not solve this issue, even if suggested by the Guided Fault Finding. Claims for replaced parts will be subject to review.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	9638		
Damage Code:	0040		
Diagnostic Time:	GFF	0150 0000	Time stated on diagnostic protocol (Max 20 TU)
	Road test prior to the service procedure	No allowance	0 TU
	Road test after the service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2054202/1		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2054202) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2019 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.