



Tech Tips

TT 15-12-01

Date: March 2, 2012

2011-2012 3.6L Routan – Fault Codes P06DD, P000D, or P0390
After Cylinder Head Replacement

October 19, 2012: Update to Information

Verify that the oil galley bolts were transferred (see pictures below) when the cylinder head was replaced.
Replacement oil galley plugs can also be ordered in a separate kit, part number 7B0198057.

