

On-car analysis list from March 22nd, 2019
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Jetta	19	All	All	Heat Shield	Customer states noise from heat shield (untouched vehicles)
	Beetle, Tiguan LWB, Passat, Jetta	18-19	All	All	MIL-on P0456	Customer states MIL-on (MUST have P0456 in the ECM) (untouched vehicles)
	Tiguan LWB	19	All	All	MIL-on P11AD, P11AE, P11AF	Customer states MIL-on (Must have one or all of P11AD, P11AE, P11AF) (untouched vehicles)
Body	Jetta	19	All	All	Front window(s) noisy during operation	Customer states front window(s) noisy during operation (untouched vehicles)
	Jetta	19	All	All	Headliner Noise/Loose	Customer states the headliner makes noise, is loose or hangs down (untouched vehicles)
	Tiguan LWB	18-19	All	All	Sunshade Binding	Customer states the sunshade is binding (untouched vehicles)
Chassis	Jetta	19	All	All	Rear Speed Sensor	Customer states MIL-on and/or multiple warning lights (MUST include any of the following faults associated with the rear wheel speed sensor: C101C01, C101D01, C101C11, C101D11, C101C12, C101D12, C101C14, C101D14, C101C29, C101D29, C10E2F0) (untouched vehicles)