

On-car analysis list from September 18th, 2017
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Passat	13	3.6L (CDVB)	All	MIL-on P0420 and/or P0430	MIL-on P0420 and/or P0430 in the ECM (untouched vehicles)
	Golf Sportwagen (Alltrack only)	17	All	All	MIL-on P0463 and B103E1B	MIL-on P0463 and B103E1B stored (untouched vehicles)
	Jetta, Passat	16-18	All	All	MIL-on P0442	MIL-on P0442 in the ECM (FAULT MUST BE ACTIVE NOT SPORADIC) (untouched vehicles)
	Jetta	17	1.4T (CZTA)	All	Fuel Gauge	Fuel gauge drops to empty with fault B103E1B (untouched vehicles)
Chassis	Jetta	17	All	All	MIL-on P0556	MIL-on P0556 in the ECM (untouched vehicles)
	Jetta	17	All	All	Rear Wheel Speed Sensor	ABS warning light with faults VAG00290 and/or VAG00287 in the ABS module (untouched vehicles)
Body	Passat	17	1.8T (CPRA)	All	Noise from Dash	Customer states noise from passenger side of dash (untouched vehicles) (A/C line must be contacting right side frame rail)
Electrical	Jetta	17	1.4T (CZTA)	All	MIL-on P068A	MIL-on P068A in the ECM (untouched vehicles)