

On-car analysis list from September 27th, 2017
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Passat	13	3.6L (CDVB)	All	MIL-on P0420 and/or P0430	MIL-on P0420 and/or P0430 in the ECM (untouched vehicles)
	Golf Sportwagen (Alltrack only)	17	All	All	MIL-on P0463 and B103E1B	MIL-on P0463 and B103E1B stored (untouched vehicles)
	Jetta, Passat	16-18	All	All	MIL-on P0442	MIL-on P0442 in the ECM (FAULT MUST BE ACTIVE NOT SPORADIC) (untouched vehicles)
Chassis	Jetta	17	All	All	MIL-on P0556	MIL-on P0556 in the ECM (untouched vehicles)
	Jetta	17	All	All	Rear Wheel Speed Sensor	ABS warning light with faults VAG00290 and/or VAG00287 in the ABS module (untouched vehicles)
Body	Passat	17	1.8T (CPRA)	All	Noise from Dash	Customer states noise from passenger side of dash (untouched vehicles) (A/C line must be contacting right side frame rail)
Electrical	Jetta	17	1.4T (CZTA)	All	MIL-on P068A	MIL-on P068A in the ECM (untouched vehicles)