

On-car analysis list from June 6th, 2017
please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Passat	13	3.6L (CDVB)	All	MIL-on P0420 and/or P0430	MIL-on P0420 and/or P0430 in the ECM (untouched vehicles)
	Touareg	16-17	All	All	Coolant leak from coolant pump	Coolant leak from the coolant pump (untouched vehicles)
	Passat, Beetle, Jetta, Golf/GTI, Sportwagen	15-17	1.8T & 2.0T EA888 Gen 3	All	Oil pressure light with P164D	Oil pressure light with P164D in the ECM (Must have fault in the ECM)
Chassis	Jetta	16-17	All	All	Rear Brake Caliper	Rear brake noise, dragging, excessive dust (untouched vehicles)
	Jetta	17	All	All	Rear Wheel Speed Sensor	ABS warning light with faults VAG00290 and/or VAG00287 in the ABS module (untouched vehicles)
	Jetta	17	All	All	Brake Hissing	Hissing noise when pressing the brake pedal (untouched vehicles)
Body	Jetta, Beetle	16 - 17	All	All	A/C Inoperative	A/C inoperative, compressor found to be locked up (compressor has to be seized) (untouched vehicles)
	Jett, Passat	17	1.8T (CPRA) 1.4T (CZTA	All	Noise from Dash	Customer states noise from passenger side of dash (untouched vehicles) (A/C line must be contacting right side frame rail)
	Jetta	17	All	All	Cracked Windshield	Customer states windshield is cracked (Vehicles below 10,000 miles with no obvious outside damage)
Electrical	Passat, Jetta, Golf/GTI, Golf Sportwagen	17	All	All	KESY Start Concerns	Keyless faulty/Keyless defective error messages with fault(s) B117213/B117313/B117413
	Golf R	17	All	All	Adaptive Cruise Fault	Error message in MFI with fault code C110300 in Address 13